

03560.002982



CofC
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Gen NAKAMURA

Application No.: 10/044,937

Filed: January 15, 2002

For: SEMICONDUCTOR MANUFACTURING
APPARATUS

U.S. Patent No. 6,810,299 B2

Issued: October 26, 2004

)
:
)
:
)
:
)
:
)
:
)

Certificate
JAN 21 2005
of Correction

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

Patentee requests that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

01/12/2005 NNGUYEN2 00000028 6810299

01 FC:1811

100.00 0P

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for that purpose.

Patentee's undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,



Attorney for Patentee
Steven E. Warner
Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
SEW/eab

DC_MAIN 188974v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,810,299 B2

DATED : October 26, 2004

INVENTOR(S): Gen NAKAMURA

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE:

In item "(57) ABSTRACT," line 2, the first occurrence of "light" should read -- light of -- and line 3, "source" should read -- source. --.

COLUMN 6:

Line 36, "In the" should read -- In --.

COLUMN 7:

Line 34, "75 to" should read -- 750 to --.

COLUMN 9:

Line 67, "z driving" should read -- Z driving --.


MAILING ADDRESS OF SENDER:

PATENT NO. 6,810,299 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,810,299 B2

DATED : October 26, 2004

INVENTOR(S): Gen NAKAMURA

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 62, "etc.)" should read -- etc.). --

COLUMN 11:

Line 63, "only on" should read -- only one --.

COLUMN 12:

Line 45, "items." should read -- item, --.

COLUMN 13:

Line 38, "there" should read -- their --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,810,299 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,810,299 B2

DATED : October 26, 2004

INVENTOR(S) Gen NAKAMURA

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 31, "taken in" should read -- taken-in --.

Line 67, "said'" should read -- said --.

COLUMN 15:

Line 9, "taken in" should read -- taken-in --.

Line 12, "software-provides" should read -- software provides --.

COLUMN 16:

Line 26, "Networks," should read -- Network, --.

Line 39, "semiconductor" should read -- the semiconductor --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,810,299 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

No. of add'l. copies
@ 30¢ per page

